

Canadian Airworthiness Directives

Number: CF-2017-18

Subject: ATA 30 - Windows – Windshield Cracking

Applicability: Bombardier Inc. model DHC-8-400, -401 and -402 aeroplanes

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-2017-18-E.pdf>

Number: CF-2017-04R1

Subject: ATA 28 - Fuel System – Corrosion and Wear of Hydraflow Couplings and Sleeves, Fuel Tube End Ferrules, and Fuel Component End Ferrules

Applicability: Bombardier Inc. model DHC-8-400, -401 and -402 aeroplanes

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-2017-04R1-E.pdf>

Number: CF-1990-06R2

Subject: ATA 67 - Tail Rotor Control – Cracking of Tail Rotor Pitch Change Chain

Applicability: Bell Helicopter Textron Inc. model 204B helicopters

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-1990-06R2-E.pdf>