

Foreign Airworthiness Directives

Number: US2018-21-01

Subject: ATA 72 - TURBINE SECTION - SECOND STAGE LOW PRESSURE TURBINE (LPT2) ROTOR BLADES - INSPECTION / REPLACEMENT

Applicability: Honeywell International Inc. (Honeywell) AS907-1-1A turbofan engines

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2018-21-01.PDF>

Number: US2018-20-24

Subject: ATA 05 - TIME LIMITS / MAINTENANCE CHECKS & ATA 28 - FUEL

Applicability: Boeing Model 737-600, 700, 800, 900 and 900ER airplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2018-20-24.PDF>

Number: US2018-20-15

Subject: ATA 24 - ELECTRICAL POWER - DEACTIVATION OF ELECTRICAL POWER - INSTALLATION OF NEW GENERATOR CONTROL UNIT (GCU) SOFTWARE

Applicability: Boeing Model 787-8 and 787-9 airplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2018-20-15.PDF>

Number: US2018-21-08

Subject: ATA 53 - FUSELAGE - STATION 259.5 FRAME WEB CRACKING - INSPECTION / REPAIR

Applicability: Boeing Model 737-100, -200, -200C, -300, -400 and -500 series airplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2018-21-08.PDF>

Number: EU2018-0225-E

Subject: ATA 25 – EQUIPMENT & FURNISHINGS – HOOK MOUNT ASSEMBLY – INSPECTION

Applicability: MBB-BK117 helicopters

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2018-0225-E.PDF>

Number: EU2018-0223

Subject: ATA 25 – EQUIPMENT / FURNISHING – SEAT ENERGY ABSORBER ASSEMBLY – MODIFICATION

Applicability: B/E Aerospace Fischer GmbH - Common Seats 170/260 H160, Known to be installed on: EC135, EC635 AS 332 L1 and EC225 LP helicopters .

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2018-0223.PDF>

Number: AUAD-GA8-10

Subject: ATA 05 - TIME LIMITS / MAINTENANCE CHECKS - NEW REVISED AIRWORTHINESS LIMITATIONS

Applicability: GIPPSLAND GA8 and GA8-TC-320 aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/AUAD-GA8-10.PDF>

Number: US2018-20-13

Subject: ATA 28 - FUEL SHUTOFF VALVES, FAILED MOTOR-OPERATED VALVE (MOV) ACTUATORS

Applicability: Boeing Model 737-600, -700, -700C, -800, -900, -900ER, Model 757-200, -200PF, -200CB, -300 and Model 767-200, -300, -300F, -400ER series airplanes.

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2018-20-13.PDF>

Number: EU2018-0222

Subject: ATA 27 – FLIGHT CONTROLS – RUDDER SHAFT ASSEMBLY RIVET CONFIGURATION – INSPECTION

Applicability: PILATUS AIRCRAFT Ltd, PC-6 aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2018-0222.PDF>

Number: EU2018-0226

Subject: ATA 55 - STABILIZERS CENTER BOX TOP SKIN - INSPECTION / REPAIR

Applicability: A330 and A340 aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2018-0226.PDF>

Number: EU2018-0230

Subject: ATA 42 – INTEGRATED MODULAR AVIONICS – AIRCRAFT MANAGEMENT COMPUTER SOFTWARE – MODIFICATION

Applicability: MBB-BK117 D-2 helicopters

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2018-0230.PDF>

Number: US2018-22-04

Subject: ATA 27 - FLIGHT CONTROL SYSTEMS - TO DETECT AND REPLACE FLAP ROTARY ACTUATORS HAVING INCORRECT ASSEMBLY.

Applicability: Boeing 787-8 and 787-9.

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2018-22-04.PDF>

Number: EU2018-0231

Subject: ATA 05 – TIME LIMITS / MAINTENANCE CHECKS – AIRWORTHINESS LIMITATIONS SECTION – PART 5 – FUEL AIRWORTHINESS LIMITATIONS – AMENDMENT

Applicability: AIRBUS A318, A319, A320 and A321 aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2018-0231.PDF>