

**Transport Canada / Transports Canada  
Civil Aviation / Aviation Civile**

**\*\* Le texte français suit l'anglais. \*\***

The following has recently been posted to the [Transport Canada AD website](#):

**Number:** EU2020-0087

**Subject:** **ATA 52 – DOORS – SIDE STAIRWAY DOOR LOCKING SAFETY MECHANISM – INSPECTION / RECONDITIONING / MODIFICATION**

**Applicability:** Airbus Helicopters SA 330, AS 332 and EC 225 helicopters

**Link:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2020-0087.PDF>

**Number:** BZ2020-04-01

**Subject:** **ATA 56 - WINDOWS - CRACKS, DELAMINATION AND FAILURE OF THE COCKPIT SIDEWINDOWS**

**Applicability:** Embraer S.A. model EMB-545 and EMB-550 airplanes

**Link:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/BZ2020-04-01.PDF>

**Number:** US2020-08-04

**Subject:** **ATA 72 - TURBINE SECTION - FAILURE OF CERTAIN LPT 3RD-STAGE BLADES**

**Applicability:** International Aero Engines, LLC (IAE) PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1129G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM model turbofan engines

**Link:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2020-08-04.PDF>

For further information on **e-Bulletin**, you may wish to visit:

<http://www.tc.gc.ca/eng/civilaviation/opssvs/management/services-referencecentre-menu-113.htm> . You can also contact Transport Canada's Civil Aviation Communications Centre at 1-800-305-2059 or at [services@tc.gc.ca](mailto:services@tc.gc.ca) for questions regarding this service.

\*\*\*\*\*  
\*\*\*\*\*

Les informations suivantes ont été récemment publiées sur le [site Web des consignes de navigabilité de Transports Canada](#) : Le sujet et l'applicabilité sont alimentés à partir du document original. Les informations provenant de sources étrangères ne sont pas soumises à la Loi sur les langues officielles, il n'y a donc pas de traduction disponible.

**Numéro:** EU2020-0087

**Sujet:** **ATA 52 – DOORS – SIDE STAIRWAY DOOR LOCKING SAFETY MECHANISM – INSPECTION / RECONDITIONING / MODIFICATION**

**Applicabilité:** Airbus Helicopters SA 330, AS 332 and EC 225 helicopters

**Lien:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2020-0087.PDF>

**Numéro:** BZ2020-04-01

**Sujet:** **ATA 56 - WINDOWS - CRACKS, DELAMINATION AND FAILURE OF THE COCKPIT SIDEWINDOWS**

**Applicabilité:** Embraer S.A. model EMB-545 and EMB-550 airplanes

**Lien:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/BZ2020-04-01.PDF>

**Numéro:** US2020-08-04

**Sujet:** ATA 72 - TURBINE SECTION - FAILURE OF CERTAIN LPT 3RD-STAGE BLADES

**Applicabilité:** International Aero Engines, LLC (IAE) PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1129G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM model turbofan engines

**Lien:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2020-08-04.PDF>