Canadian Airworthiness Directives

Number: CF-2018-18
Subject: TAIL ROTOR DRIVE – LOOSE TAIL ROTOR GEARBOX
Applicability: Bell Helicopter Textron Canada Limited (BHTCL) model 429 Helicopters, serial numbers 57001 through 57321, 57323 through 57341, 57343 through 57346, 57348, and 57350.
Link: http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-2018-18-E.pdf