

The following has recently been posted to the [Transport Canada AD website](#):

Les informations suivantes ont été récemment publiées sur le [site Web des consignes de navigabilité de Transports Canada](#). Le sujet et l'applicabilité sont alimentés à partir du document original. Les informations provenant de sources étrangères ne sont pas soumises à la Loi sur les langues officielles, il n'y a donc pas de traduction disponible.

Foreign Airworthiness Directive / Consignes de navigabilité étrangère

Number / Numéro: EU 2016-0238

Subject / Sujet : ATA 53 – Fuselage – Door Stop Fitting Holes at Frames 66/68 – Inspection / Repair

Applicability / Applicabilité: Airbus A318, A319, A320 and A321 aeroplanes

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0238.pdf>

Number / Numéro: US 2016-26-04

Subject / Sujet : ATA 62, Main Rotor Blades

Applicability / Applicabilité: Robinson Model R44, R44 II & R66 helicopters

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-26-04.pdf>

Number / Numéro: EU 2016-0254

Subject / Sujet : ATA 73 - Engine Fuel & Control - Fuel Injection System Control Unit - Modification / Software Update

Applicability / Applicabilité: SOLO KLEINMOTOREN Model 2625 engines

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0254.pdf>

Number / Numéro: US 2016-25-07

Subject / Sujet : ATA 53, Fuselage

Applicability / Applicabilité: Boeing Model 767-200 and -300 series airplanes

Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-25-07.pdf>

Number / Numéro: US 2016-25-01

Subject / Sujet : ATA 22 - Uncommanded autopilot engagement events resulting in incorrect stabilizer trim adjustment during takeoff.

Applicability / Applicabilité: Boeing 747, 757, 767

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-25-01.pdf>

Number / Numéro: US 2016-25-29

Subject / Sujet : ATA 25 - Fire in the bilge area of the cargo compartment

Applicability / Applicabilité: Boeing 767-200, and -300.

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-25-29.pdf>

Number / Numéro: US 2016-25-21

Subject / Sujet : ATA 21 - Modification of Cabin Air Compressor (CAC) modules on LH and RH Cabin Air Conditioning and Temperature Control System (CACTCS) packs

Applicability / Applicabilité: Boeing B787-8 airplanes

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-25-21.pdf>

Number / Numéro: US 2016-25-02

Subject / Sujet : ATA 27 - Flight Controls - Degraded Performance of Flight Control Power Control Units (PCU) Electro-Hydraulic Servo Valves (EHSV) due to reduced RHSV internal hydraulic supply pressure

Applicability / Applicabilité: Boeing model 787-8 airplanes

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-25-02.pdf>

Number / Numéro: EU 2016-0260

Subject / Sujet : ATA 63 - Main rotor Drive - NR Indicator - Check / Modification

Applicability / Applicabilité: Airbus Helicopters AS 350 B2 Helicopters

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0260.pdf>

Number / Numéro: EU 2016-0261

Subject / Sujet : ATA 26 - fire Protection - Fire Extinguisher Bottles - Inspection / Replacement

Applicability / Applicabilité: Leonardo S.p.A A109LUH, A109E, A109s and AW109SP helicopter, all serial numbers

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0261.pdf>

Number / Numéro: US 2016-25-05

Subject / Sujet : ATA 55 - Stabilizers - Inspection / Repair of Cracking in Horizontal Stabilizers

Applicability / Applicabilité: Boeing 747-100, -200, -300, -400, -SR and -SP series airplanes

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-25-05.pdf>

Number / Numéro: EU 2016-0259

Subject / Sujet : ATA 28 - fuel - Fuel Hoses - Inspection / Replacement

Applicability / Applicabilité: DG-Flugzeugbau DG-500M, DG-500 MB, DG-800 A, DG-800 LA, DG-800 B, DG-400 and DG-600 powered sailplanes, all serial numbers

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0259.pdf>

Number / Numéro: EU 2016-0256

Subject / Sujet : ATA 25 - Equipment / Furnishings - Pilot and Co-pilot Seats - Modification and Re-identification with new P/N

Applicability / Applicabilité: IPECO HOLDING Ltd. Type 3A063 flight crew seats, identified by Part number (P/N) in Appendix 1 of this AD, all serial numbers. These seats are known to be installed on, but not limited to, ATR-GIE Avions de Transport Régional ATR 42 and ATR 72 aeroplanes.

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0256.pdf>

Number / Numéro: EU 2016-0258

Subject / Sujet : ATA 33 - Lights - Strobe Light Harnesses - Inspection / Modification

Applicability / Applicabilité: Airbus Helicopters AS 365 N2 and As365 N3 Helicopters

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0258.pdf>

Number / Numéro: EU 2016-0257

Subject / Sujet : ATA 71 - Power Plant - CFM56 Engines Fan Cowl Door latch with key and Flag - Modification

Applicability / Applicabilité: Airbus A318, A319, A320 and A321 aeroplanes

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0257.pdf>

Number / Numéro: EU 2016-0255

Subject / Sujet : ATA 63 - Main Rotor Drive - Main Gearbox Input Module - Replacement

Applicability / Applicabilité: Leonardo S.p.A. AB139 and AW 139 helicopters

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0255.pdf>

Number / Numéro: EU 2016-0250

Subject / Sujet : ATA 51 - Structures - Fuselage Section T5 Lateral Panels - Inspection

Applicability / Applicabilité: Dassault Aviation Falcon 7X aeroplanes, serial number (s/n) 2 to 19 inclusive, except s/n 3 and s/n 18

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0250.pdf>

Number / Numéro: EU 2016-0246

Subject / Sujet : ATA 65 - Tail Rotor Drive - Tail Gearbox Central Housing - Dimensional Check / Replacement

Applicability / Applicabilité: Agusta AB139 and AW139 Helicopters

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0246.pdf>
