

## Canadian Airworthiness Directives

**Number:** CF-2017-23

**Subject:** ATA 25 - Furnishings/Equipment – Hoist Overload Clutch Slippage or Cable Rupture

**Applicability:** BHTC helicopters:

Model 429, serial number 57001 and subsequent with Goodrich 44316 Series Hoist System installed.

Model 430, serial number 49001 and subsequent with Goodrich 42325 Series Hoist System installed.

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-2017-23-E.pdf>

**Number:** CF-2017-24

**Subject:** ATA 27 - Horizontal Stabilizer Trim Actuator – Attachment Pins and Trunnions Not Serialized

**Applicability:**

Bombardier Inc. aeroplanes:

Model CL-600-1A11 (600), serial numbers 1002 and 1004 through 1085;

Model CL-600-2A12 (601 Variant), serial numbers 3001 through 3066;

Model CL-600-2B16 (601-3A/-3R Variant), serial numbers 5001 through 5194;

Model CL-600-2B16 (604 Variant), serial numbers 5301 through 5665, 5701 through 5990, 6050 and subsequent.

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-2017-24-E.pdf>