

## **Foreign Airworthiness Directives**

**Number:** EASA 2017-0138

**Subject:** ATA 71 – Powerplant – Aft Engine Mounts Retainers – Inspection / Replacement

**Applicability:** Airbus, Models A318, A319, A320, and A321 aeroplanes

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0138.pdf>

**Number:** NZ DCA-DH60-111

**Subject:** ATA - 57 - Wings

**Applicability:** Emergency Airworthiness Directive - De Havilland, Model DH83 Fox Moth airplanes

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/NZDCA-DH60-111-E.pdf>

**Number:** NZ DCA-DH82-129

**Subject:** ATA - 57 - Wings

**Applicability:** Emergency Airworthiness Directive - De Havilland, Model DH82A Tiger Moth airplanes

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/NZDCA-DH82-129-E.pdf>

**Number:** NZ DCA-DH83-105

**Subject:** ATA - 57 - Wings

**Applicability:** Emergency Airworthiness Directive - De Havilland, Model DH83 Fox Moth airplanes

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/NZDCA-DH83-105-E.pdf>

**Number:** EASA 2017-0144

**Subject:** ATA 30 – Ice and Rain Protection – Horizontal Stabilizer De-Icing Boots – Inspection / Replacement. Aircraft Flight Manual – Amendment

**Applicability:** SAAB SF340A aeroplanes

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0144.pdf>

**Number:** EASA 2017-0143

**Subject:** ATA 24 – Electrical Power – Direct Current (Optional) Second Battery – Replacement

**Applicability:** Airbus AS 350 Helicopters

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0143.pdf>

**Number:** EASA 2017-0142

**Subject:** ATA 52 – Doors – Main Entrance Door Placard – Installation / Replacement

**Applicability:** Fan Jet Falcon, Mystère-Falcon 20, Mystère-Falcon 200 and Mystère-Falcon 50 aeroplanes

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0142.pdf>

**Number:** FAA 2017-16-03

**Subject:** ATA 57 - Wing Spar - aft wing spar cracking

**Applicability:** Piper, PA-46-600TP (M600) airplanes

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-16-03.pdf>

**Number:** EASA 2017-0147

**Subject:** ATA 67 – Rotors Flight Control – Tail Rotor Controls – Modification

**Applicability:** Airbus Helicopters EC135 and EC635 helicopters

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0147.pdf>