

Foreign Airworthiness Directives

Number: FAA 2017-16-11

Subject: ATA 82 - Reciprocating Engine Power Section - Connecting rod failure.

Applicability: Lycoming Engines listed in Lycoming MSB No. 632B.

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-16-11.pdf>

Number: NZ DCA-DH60-111A

Subject: De Havilland, Model DH83 Fox Moth airplanes

Applicability: ATA - 57 - Wings

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/NZDCA-DH60-111A.pdf>

Number: NZ DCA-DH82-129A

Subject: ATA - 57 - Wings

Applicability: Emergency Airworthiness Directive - De Havilland, Model DH82A Tiger Moth airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/NZDCA-DH82-129A.pdf>

Number: NZ DCA-DH83-105A

Subject: ATA - 57 - Wings

Applicability: De Havilland, Model DH83 Fox Moth airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/NZDCA-DH83-105A.pdf>

Number: EASA 2017-0150

Subject: ATA 35 – Oxygen – Crew Oxygen / Oxygen Pipe Corrosion – Inspection

Applicability: Airbus A318, A319, A320 and A321 aeroplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0150.pdf>

Number: EASA 2017-0152

Subject: ATA 28 – Fuel – Trim Tank Overflow – Functional Test

Applicability: Airbus A330 and A340 aeroplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0152.pdf>

Number: EASA 2017-0153

Subject: ATA 32 – Landing Gear – Parking Brake Operated Valve – Replacement

Applicability: Airbus A300, A310, A300-600 and A300-600ST aeroplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0153.pdf>