

Foreign Airworthiness Directives

Number: EASA 2018-0046

Subject: ATA 65 – TAIL ROTOR DRIVE – TAIL GEAR BOX – INSPECTION / REPLACEMENT

Applicability: Airbus Helicopters Deutschland GmbH, MBB-BK117 helicopters

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2018-0046.pdf>

Number: EASA 2018-0044

Subject: ATA 72 – ENGINE – GAS GENERATOR (MODULE 02) / POWER TURBINE WHEEL – REPLACEMENT

Applicability: SAFRAN (Turboméca) ARRIUS 2B1, 2B1A, 2B2, 2G1, 2K1 & 2K2 engines, all serial numbers (s/n).

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2018-0044.pdf>