

Foreign Airworthiness Directives

Number: EASA 2015-0135R2

Subject: **ATA 34 –NAVIGATION – ANGLE OF ATTACK SENSORS – REPLACEMENT**

Applicability: Airbus, Model A318, A319, A320 and A321 aeroplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2015-0135R2.pdf>

Number: FAA 2018-04-06

Subject: **ATA 53 - FUSELAGE - CRACKING OF THE STATION (STA) 348.2 FRAME**

Applicability: Boeing, Model 737-100, -200, -200C, -300, -400, and -500 series airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2018-04-06.pdf>

Number: FAA 2018-04-07

Subject: **ATA 53 - FUSELAGE - FATIGUE CRACKING IN TRANSPORT CATEGORY AIRPLANES**

Applicability: Boeing, Model 747-100, -200, -300, -400, SR and SP series airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2018-04-07.pdf>

Number: NZ DCA-DH60-111B

Subject: **ATA - 57 - WING/AILERON SPARS - INSPECTION**

Applicability: De Havilland, Model DH60 Fox Moth airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/NZDCA-DH60-111B.pdf>

Number: NZ DCA-DH82-129B

Subject: **ATA - 57 - WING/AILERON SPARS - INSPECTION**

Applicability: De Havilland, Model DH82 Tiger Moth airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/NZDCA-DH82-129B.pdf>

Number: NZ DCA-DH83-105B

Subject: **ATA - 57 - WING/AILERON SPARS - INSPECTION**

Applicability: De Havilland, Model DH83 Fox Moth airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/NZDCA-DH83-105B.pdf>

Number: FAA 2018-04-08

Subject: **ATA 53 - FUSELAGE - DETECT AND CORRECT CRACKING IN THE GORE WEBS**

Applicability: Boeing, Model 737-100, -200, -200C, -300, -400, and -500 airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2018-04-08.pdf>