

Foreign Airworthiness Directives

Number: EASA 2018-0071

Subject: ATA 72 – ENGINE – FAN BLADES – INSPECTION

Applicability: CFM International S.A CFM56-7B Engines

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2018-0071.pdf>

Number: EASA 2018-0080

Subject: ATR 42 AND ATR 72 AEROPLANES

Applicability: ATA 32 – Landing Gear – Main Landing Gear Universal Joints – Inspection / Replacement

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2018-0080.pdf>

Number: EASA 2016-0142R1

Subject: ATA 62 – MAIN ROTOR – SWASHPLATE ASSEMBLY – REPLACEMENT / INSPECTION

Applicability: AIRBUS Helicopters - MBB-BK 117 and BO105 helicopters

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0142R1.pdf>

Number: EASA 2018-0083

Subject: ATA 05 – TIME LIMITS / MAINTENANCE CHECKS – AIRWORTHINESS LIMITATIONS SECTION – AMENDMENT

Applicability: Dassault Aviation - Fan Jet Falcon aeroplanes, all serial numbers

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2018-0083.pdf>

Number: FAA 2018-07-18

Subject: ATA 53 - FUSELAGE - INSPECT TO DETECT AND CORRECT MISSING FASTENERS IN STRINGER 37 (S-37L AND S-37R) LAP SPLICE BETWEEN BODY STATIONS 428 AND 431

Applicability: Boeing Model 767-200, -300, -300F, and -400ER series airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2018-07-18.pdf>

Number: FAA 2018-07-19

Subject: ATA 32 - LANDING GEAR - INSPECTION OF PARKING BRAKE AND ALTERNATE PITCH TRIM MODULE (PBM) TO PREVENT AN UNINTENDED PARKING BRAKE RELEASE

Applicability: Boeing Model 787-8 and 787-9 airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2018-07-19.pdf>

Number: EASA 2017-0064R2

Subject: EMERGENCY AD - ATA 73 – ENGINE FUEL & CONTROL – DRAIN VALVE ASSEMBLY – INSPECTION / REPLACEMENT

Applicability: SAFRAN, Model ARRIEL 1 engines

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0064R2.pdf>