

## **Canadian Airworthiness Directives**

**Number:** CF-2018-12

**Subject:** ENGINE – MATERIAL ANOMALY FOR CERTAIN HIGH PRESSURE (HP) CENTRIFUGAL IMPELLERS

**Applicability:** Pratt & Whitney Canada (P&WC) model PW150A engines that have HP centrifugal impellers with serial numbers listed in table 1 and 2 of P&WC Service Bulletin (SB) 35331 revision 1.

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-2018-12-E.pdf>

**Number:** CF- 2018-13

**Subject:** EQUIPMENT/FURNISHING - PASSENGER SEATS – UNSECURED PASSENGER SAFETY LAP BELTS

**Applicability:** Diamond Aircraft model DA 62 aeroplanes, serial numbers 62.009, 62.011, 62.016, 62.017, 62.018, 62.019, 62.022, 62.023, 62.024, 62.027, 62.028, 62.029, 62.033, 62.035, 62.036, 62.039, 62.040, 62.042 through 62.047, 62.049, 62.050, 62.051, 62.052, 62.054, 62.055, 62.057, 62.058, 62.059, 62.061, 62.063 through 62.079, 62.C002 and 62.C004.

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-2018-13-E.pdf>

**Number:** CF-2018-14

**Subject:** FUSELAGE - BELLY FAIRING - BLOCKED DRAINAGE HOLES

**Applicability:** Bombardier Inc. model BD-700-1A10 and BD-700-1A11 aeroplanes, serial numbers 9001 through 9707, 9709 through 9717, 9719 through 9726, 9728, 9730, 9732 through 9734, 9736 through 9740, 9742 through 9745, 9749, 9751, 9757, and 9998.

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-2018-14-E.pdf>