

## **Foreign Airworthiness Directives**

**Number:** EASA 2018-0133C1

**Subject:** ATA 79 – OIL – OIL COOLER AIR INDUCTION DUCT – MODIFICATION

**Applicability:** DAHER AEROSPACE, TBM 700 aeroplanes

**Link:** <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2018-0133.pdf>

**Number:** EASA 2018-0135

**Subject:** ATA 32 – LANDING GEAR – MAIN LANDING GEAR SLIDING TUBE – INSPECTION / REPLACEMENT

**Applicability:** Airbus A318, A319, A320 and A321 aeroplanes

**Link:** <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2018-0135.pdf>

**Number:** EASA 2018-0136

**Subject:** ATA 32 – LANDING GEAR – MAIN LANDING GEAR SLIDING TUBE – INSPECTION

**Applicability:** Airbus A318, A319 and A320 aeroplanes

**Link:** <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2018-0136.pdf>

**Number:** EASA 2014-0236R1

**Subject:** ATA 33 - LIGHTS – EMERGENCY LIGHTING ROTORCRAFT FLIGHT MANUAL AMENDMENT/ OPERATIONAL PROCEDURE

**Applicability:** Airbus Helicopters SA 365, AS 365 and EC 155 helicopters

**Link:** <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2014-0236r1.pdf>

**Number:** EASA 2018-0137

**Subject:** ATA 54 – NACELLES / PYLONS – PYLON AFT FIXED FAIRINGS – INSPECTION

**Applicability:** Airbus A318, A319, A320, and A321 aeroplanes

**Link:** <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2018-0137.pdf>