

Foreign Airworthiness Directives

Number: FAA 2018-16-07

Subject: ATA 72 - TURBINE SECTION, UNAPPROVED WELDS, HPT CASE

Applicability: GENERAL ELECTRIC COMPANY (GE) GENx 1B ALL SERIES AND GENx 2B ALL SERIES ENGINES

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2018-16-07.pdf>

Number: US2018-16-09

Subject: ATA 53 - FUSELAGE - FUSELAGE FRAME WEB CRACKING

Applicability: Boeing Model 737-100, -200, -200C, -300, -400, and -500 series airplanes

Link: <HTTPS://WWWAPPS.TC.GC.CA/SAF-SEC-SUR/2/AWD-CN/DOCUMENTS/US2018-16-09.PDF>

Number: US2018-16-05

Subject: ATA 57 - WINGS - DETECT AND CORRECT CRACKING IN THE WING UPPER SKIN AND FORWARD DRAG FITTINGS

Applicability: Boeing Model 757-200, -200PF, -200CB, and -300 series airplanes

Link: <HTTPS://WWWAPPS.TC.GC.CA/SAF-SEC-SUR/2/AWD-CN/DOCUMENTS/US2018-16-05.PDF>

Number: US2018-16-06

Subject: ATA 25, EQUIPMENT/FURNISHINGS; 53, FUSELAGE - DETECT AND REPLACE BMS 8-39 FLEXIBLE URETHANE FOAM IN CERTAIN AREAS

Applicability: Boeing Model 747-100, -100B, -100B SUD, -200B, -200C, -200F, -300, -400, -400D, 747SP, and 747SR series airplanes

Link: <HTTPS://WWWAPPS.TC.GC.CA/SAF-SEC-SUR/2/AWD-CN/DOCUMENTS/US2018-16-06.PDF>