

**Transport Canada / Transports Canada
Civil Aviation / Aviation Civile**

**** Le texte français suit l'anglais. ****

The following has recently been posted to the [Transport Canada AD website](#):

Number: US2017-12-07

Subject: ATA 21 - AIR CONDITIONING - TEMPERATURE CONTROL VALVE / CONTROL CABIN TRIM AIR MODULATING VALVE - REPLACEMENT

Applicability: The Boeing Company Model 737-800, -900, and -900ER series airplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2017-12-07.PDF>

Number: US2019-23-14

Subject: ATA 28 - FUEL - AIRWORTHINESS LIMITATIONS (AWL) FUEL TANK IGNITION PREVENTION AND NITROGEN GENERATION SYSTEM (NGS) - NEW / REVISED

Applicability: The Boeing Company Model 737-100, -200, -200C, -300, -400 and -500 series airplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-23-14.PDF>

Number: US2020-01-11

Subject: ATA 21 - AIR CONDITIONING - TEMPERATURE CONTROL VALVE / CONTROL CABIN TRIM AIR MODULATING VALVE - REPLACEMENT

Applicability: The Boeing Company Model 737-800, -900, and -900ER series airplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2020-01-11.PDF>

Number: US2020-01-55

Subject: Emergency AD - ATA 72 - ENGINE - HIGH PRESSURE TURBINE (HPT) FAILURE - INTERSTAGE SEAL - REMOVE / REPLACE

Applicability: General Electric Company (GE) GE90-110B1 and GE90-115B model turbofan engines

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2020-01-55.PDF>

Number: EU2020-0008

Subject: ATA 27 - FLIGHT CONTROLS - FLAP CONTROL SYSTEM / BELLCRANK ASSEMBLY - INSPECTION / MODIFICATION

Applicability: Diamond Aircraft Industries GmbH DA 42 and DA 42 M aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2020-0008.PDF>

Les informations suivantes ont été récemment publiées sur le [site Web des consignes de navigabilité de Transports Canada](#) : Le sujet et l'applicabilité sont alimentés à partir du document original. Les informations provenant de sources étrangères ne sont pas soumises à la Loi sur les langues officielles, il n'y a donc pas de traduction disponible.

Numéro: US2017-12-07

Sujet: ATA 21 - AIR CONDITIONING - TEMPERATURE CONTROL VALVE / CONTROL CABIN TRIM AIR MODULATING VALVE - REPLACEMENT

Applicabilité: The Boeing Company Model 737-800, -900, and -900ER series airplanes

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2017-12-07.PDF>

Numéro: US2019-23-14

Sujet: ATA 28 - FUEL - AIRWORTHINESS LIMITATIONS (AWL) FUEL TANK IGNITION PREVENTION AND NITROGEN GENERATION SYSTEM (NGS) - NEW / REVISED

Applicabilité: The Boeing Company Model 737-100, -200, -200C, -300, -400 and -500 series airplanes

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-23-14.PDF>

Numéro: US2020-01-11

Sujet: ATA 21 - AIR CONDITIONING - TEMPERATURE CONTROL VALVE / CONTROL CABIN TRIM AIR MODULATING VALVE - REPLACEMENT

Applicabilité: The Boeing Company Model 737-800, -900, and -900ER series airplanes

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2020-01-11.PDF>

Numéro: US2020-01-55

Sujet: Emergency AD - ATA 72 - ENGINE - HIGH PRESSURE TURBINE (HPT) FAILURE - INTERSTAGE SEAL - REMOVE / REPLACE

Applicabilité: General Electric Company (GE) GE90-110B1 and GE90-115B model turbofan engines

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2020-01-55.PDF>

Numéro: EU2020-0008

Sujet: ATA 27 - FLIGHT CONTROLS - FLAP CONTROL SYSTEM / BELLCRANK ASSEMBLY - INSPECTION / MODIFICATION

Applicabilité: Diamond Aircraft Industries GmbH DA 42 and DA 42 M aeroplanes

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2020-0008.PDF>