

Foreign Airworthiness Directives

Number: EU2017-0240R1

Subject: ATA 34 – NAVIGATION – BAROMETRIC SETTING – OPERATIONAL LIMITATIONS / MASTER MINIMUM EQUIPMENT LIST – AMENDMENT

Applicability: DASSAULT, Falcon 7X, 2000EX and 900EX aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2017-0240R1.PDF>

Number: EU2020-0151-E

Subject: ATA 72 – ENGINE – MODULE 03 / STAGE 2 HIGH PRESSURE TURBINE – REPLACEMENT

Applicability: Safran Helicopters Engines Arriel 1 engines

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2020-0151-E.PDF>

Number: US2020-11-01

Subject: ATA 27 - FLIGHT CONTROLS - PRIMARY FLIGHT CONTROL ACTUATION SYSTEM (PFCAS) SOFTWARE UPDATE

Applicability: Gulfstream Aerospace Corporation Model GVI airplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2020-11-01.PDF>

Number: EU2020-0153

Subject: ATA 53 – FUSELAGE – REAR FUSELAGE CLIPS, SHEAR WEBS AND ANGLES – REPLACEMENT

Applicability: Airbus A319, A320 and A321 aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2020-0153.PDF>

Number: CF-2020-24

Subject: ATA 34 - NAVIGATION - INERTIAL REFERENCE SYSTEM (IRS) / FLIGHT MANAGEMENT SYSTEM (FMS) - WRONG MAGNETIC HEADING DISPLAYED DUE TO OUTDATED MAGNETIC VARIATION (MAGVAR) TABLES

Applicability: Bombardier Inc. model CL-600-2B16 (604 Variant) aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/CF-2020-24-E.PDF>