

Foreign Airworthiness Directives

Number: FAA 2017-13-11

Subject: ATA 27, Flight controls

Applicability: Gulfstream Aerospace Corporation Model G-IV airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-13-11.pdf>

Number: EASA 2008-0165R1

Subject: ATA 62 – Rotor(s) – Starflex Star Arm Ends – Check / Replacement

Applicability: Airbus Helicopters, SA 365 N, SA 365 N1, AS 365 N2, AS 365 N3, SA 365 C, SA 365 C1, SA 365 C2, SA 365 C3 and SA 366 G1 helicopters

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2008-0165R1.pdf>

Number: EASA 2017-0116

Subject: ATA 05 – Main Gearbox Magnetic Plugs – Inspection ATA 63 – Planet Gear Assemblies – Replacement

Applicability: AIRBUS HELICOPTERS: SA 365 N, SA 365 N1, AS 365 N2, AS 365 N3 AND EC 155 B and EC 155 B1

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0116.pdf>

Number: FAA 2017-13-13

Subject: Air Transport Association (ATA) of America Code 53, Fuselage.

Applicability: The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-13-13.pdf>

Number: FAA 2017-13-14

Subject: (ATA) of America Code 25, Equipment/furnishings

Applicability: The Boeing Company Model 777-300ER series airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-13-14.pdf>

Number: EASA 2017-0117

Subject: ATA 57 – Wing – Stringer Attachments at Rib 2 to Rib 7 – Modification

Applicability: AIRBUS A318, A319, A320, and A321 aeroplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0117.pdf>

Number: EASA 2017-0118

Subject: ATA 92 – Electric / Electronic Common Installation – Wire Chafing Behind Cabin Sidewall – Inspection

Applicability: ATR 42 and ATR 72 aeroplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0118.pdf>

Number: EASA 2017-0119

Subject: ATA 32 – Landing Gear – Brake Dual Distribution Valve – Modification

Applicability: AIRBUS, A319, A320 and A321 aeroplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0119.pdf>

Number: FAA 2017-14-04

Subject: ATA 79, Engine Oil.

Applicability: Piper Aircraft, Inc. Models PA-28 PA-32 series airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-14-04.pdf>

Number: EASA 2017-0120

Subject: ATA 78 - Engine Exhaust - Exhaust Pipes - Modification / Inspection

Applicability: Diamond aircraft Industries GmbH Da42 and DA 42 M aeroplanes

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0120.pdf>