

**Transport Canada / Transports Canada  
Civil Aviation / Aviation Civile**

**\*\* Le texte français suit l'anglais. \*\***

The following has recently been posted to the [Transport Canada AD website](#):

**Number:** EU2019-0046

**Subject:** **ATA 63 – ROTOR DRIVE(S) – TAIL ROTOR DRIVE FLANGE – MODIFICATION**

**Applicability:** AIRBUS HELICOPTERS Models SA 365 N1, AS 365 N2, AS 365 N3, EC 155 B and EC 155 B1 helicopters

**Link:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0046.PDF>

**Number:** EU2019-0047

**Subject:** **ATA 05 - TIME LIMITS / MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS SECTION - AMENDMENT**

**Applicability:** Airbus A330 aeroplanes

**Link:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0047.PDF>

**Number:** EU2019-0049

**Subject:** **ATA 05 - TIME LIMITS / MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS SECTION - AMENDMENT**

**Applicability:** Airbus A330 aeroplanes

**Link:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0049.PDF>

**Number:** US2019-05-04

**Subject:** **ATA 62 - MAIN ROTOR BLADE - CRACKING - DETAILED VISUAL INSPECTION**

**Applicability:** MD Helicopters, Inc., Model 369A, 369D, 369E, 369FF, 369H, 369HE, 369HM, 369HS, 500N, and 600N helicopters

**Link:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-05-04.PDF>

\*\*\*\*\*  
\*\*\*\*\*

Les informations suivantes ont été récemment publiées sur le [site Web des consignes de navigabilité de Transports Canada](#). Le sujet et l'applicabilité sont alimentés à partir du document original. Les informations provenant de sources étrangères ne sont pas soumises à la Loi sur les langues officielles, il n'y a donc pas de traduction disponible.

**Numéro:** EU2019-0046

**Sujet:** **ATA 63 – ROTOR DRIVE(S) – TAIL ROTOR DRIVE FLANGE – MODIFICATION**

**Applicabilité:** AIRBUS HELICOPTERS Models SA 365 N1, AS 365 N2, AS 365 N3, EC 155 B and EC 155 B1 helicopters

**Lien:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0046.PDF>

**Numéro:** EU2019-0047

**Sujet:** **ATA 05 - TIME LIMITS / MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS SECTION - AMENDMENT**

**Applicabilité:** Airbus A330 aeroplanes

**Lien:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0047.PDF>

**Numéro:** EU2019-0049

**Sujet:** **ATA 05 - TIME LIMITS / MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS SECTION - AMENDMENT**

**Applicabilité:** Airbus A330 aeroplanes

**Lien:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0049.PDF>

**Numéro:** US2019-05-04

**Sujet:** ATA 62 - MAIN ROTOR BLADE - CRACKING - DETAILED VISUAL INSPECTION

**Applicabilité:** MD Helicopters, Inc., Model 369A, 369D, 369E, 369FF, 369H, 369HE, 369HM, 369HS, 500N, and 600N helicopters

**Lien:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-05-04.PDF>