

**Transport Canada / Transports Canada  
Civil Aviation / Aviation Civile**

**\*\* *Le texte français suit l'anglais.* \*\***

The following has recently been posted to the [Transport Canada AD website](#):

**Number:** US2019-23-10

**Subject:** ATA 27 - AILERON CONTROL SYSTEM - INSPECTION

**Applicability:** Textron Aviation Inc. Models E33, E33A, E33C, F33, G33, 35-C33, 35-C33A, S35, V35, V35A, 36, F33A, F33C, V35B & A36 airplanes.

**Link:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-23-10.PDF>

**Number:** US2019-22-06

**Subject:** ATA 28 - FUEL - AVIATION PARTNERS (STC) ST00830SE REINFORCEMENT ANGLE, FUEL QUANTITY INDICATING SYSTEM (FQIS) TANK UNIT CLEARANCE - INSPECTION / REPAIR

**Applicability:** The Boeing Company Model 737-800 series airplanes

**Link:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-22-06.PDF>

**Number:** US2019-21-51

**Subject:** ATA 72 - ENGINE - HIGH PRESSURE TURBINE (HPT) FAILURE - INTERSTAGE SEAL PART NUMBER 2505M72P01 - REMOVE / REPLACE

**Applicability:** General Electric Company GE90-115B model turbofan engines

**Link:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-21-51.PDF>

\*\*\*\*\*  
\*\*\*\*\*

Les informations suivantes ont été récemment publiées sur le [site Web des consignes de navigabilité de Transports Canada](#) : Le sujet et l'applicabilité sont alimentés à partir du document original. Les informations provenant de sources étrangères ne sont pas soumises à la Loi sur les langues officielles, il n'y a donc pas de traduction disponible.

**Numéro:** US2019-23-10

**Sujet:** ATA 27 - AILERON CONTROL SYSTEM - INSPECTION

**Applicabilité:** Textron Aviation Inc. Models E33, E33A, E33C, F33, G33, 35-C33, 35-C33A,

S35, V35, V35A, 36, F33A, F33C, V35B & A36 airplanes.

**Lien:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-23-10.PDF>

**Numéro:** US2019-22-06

**Sujet:** ATA 28 - FUEL - AVIATION PARTNERS (STC) ST00830SE REINFORCEMENT ANGLE, FUEL QUANTITY INDICATING SYSTEM (FQIS) TANK UNIT CLEARANCE - INSPECTION / REPAIR

**Applicabilité:** The Boeing Company Model 737-800 series airplanes

**Lien:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-22-06.PDF>

**Numéro:** US2019-21-51

**Sujet:** ATA 72 - ENGINE - HIGH PRESSURE TURBINE (HPT) FAILURE - INTERSTAGE SEAL PART NUMBER 2505M72P01 - REMOVE / REPLACE

**Applicabilité:** General Electric Company GE90-115B model turbofan engines

**Lien:** <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-21-51.PDF>