

**Transport Canada / Transports Canada
Civil Aviation / Aviation Civile**

**** Le texte français suit l'anglais. ****

The following has recently been posted to the [Transport Canada AD website](#):

Number: US2020-01-18

Subject: **ATA 05 - TIME LIMITS / MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS SECTION - REVISION**

Applicability: The Boeing Company Model 757-200, -200PF, -200CB, and -300 series airplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2020-01-18.PDF>

Number: EU2019-0279R1

Subject: **ATA 26 – FIRE PROTECTION – CARGO COMPARTMENT FIRE EXTINGUISHING PIPES – INSPECTION / MODIFICATION**

Applicability: Airbus A320 aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0279R1.PDF>

Number: EU2020-0019

Subject: **ATA 53 – FUSELAGE – LATERAL WINDOW FRAME UPPER FASTENER HOLES – INSPECTION**

Applicability: Airbus A318, A319, A320 and A321 aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2020-0019.PDF>

You are receiving this notification as a subscriber to the Transport Canada Civil Aviation e-Bulletin alert service. To unsubscribe, please use the form available on this Web page:

<http://www.tc.gc.ca/eng/civilaviation/opssvs/menu-1152.htm>

For further information on **e-Bulletin**, you may wish to visit:

<http://www.tc.gc.ca/eng/civilaviation/opssvs/management/services-referencecentre-menu-113.htm> . You

can also contact Transport Canada's Civil Aviation Communications Centre at 1-800-305-2059 or at services@tc.gc.ca for questions regarding this service.

Les informations suivantes ont été récemment publiées sur le [site Web des consignes de navigabilité de Transports Canada](#) : Le sujet et l'applicabilité sont alimentés à partir du document original. Les informations provenant de sources étrangères ne sont pas soumises à la Loi sur les langues officielles, il n'y a donc pas de traduction disponible.

Numéro: US2020-01-18

Sujet: **ATA 05 - TIME LIMITS / MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS SECTION - REVISION**

Applicabilité: The Boeing Company Model 757-200, -200PF, -200CB, and -300 series airplanes

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2020-01-18.PDF>

Numéro: EU2019-0279R1

Sujet: **ATA 26 – FIRE PROTECTION – CARGO COMPARTMENT FIRE EXTINGUISHING PIPES – INSPECTION / MODIFICATION**

Applicabilité: Airbus A320 aeroplanes

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0279R1.PDF>

Numéro: EU2020-0019

Sujet: ATA 53 – FUSELAGE – LATERAL WINDOW FRAME UPPER FASTENER HOLES – INSPECTION

Applicabilité: Airbus A318, A319, A320 and A321 aeroplanes

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2020-0019.PDF>